

COMAT

PRESS LEVELING SYSTEM

BOXPLAN

Reduce patch-up time and materials by up to 70%.

Part Number			Machine Type and Model	Base Pl.	Hardness
1	Bo	131	Bobst SP 76-E	3	S
10	Bo	131	Bobst SP 102-E	2	S
11	Bo	131	Bobst SP 102-E II/SE	3	S
15	Bo	131	Bobst SP 102-CE/R	3	S
16	Bo	131	Bobst SP 102-CE/R II	2	S
20	Bo	131	Bobst SP 103-E/R	3	S
25	Bo	131	Bobst SP 104-E/R	3	S
30	Bo	131	Bobst Spintera 106-PER	3	S
32	Bo	131	Bobst Spanthera 106-LER	3	S
35	Bo	131	Bobst SP 1080-E	3	S
50	Bo	131	Bobst SP 1260-E	3	S
55	Bo	131	Bobst SP 130-E/R	3	S
60	Bo	131	Bobst SP 1420-E/R	3	S
65	Bo	131	Bobst SP 142-E/R	3	S
70	Bo	131	Bobst SP 142-CER	3	S
71	Bo	131	Bobst SP 142-CER II	1	S
72	Bo	131	Bobst SP 145 Spanthera	3	S
76	Bo	131	Bobst SP 1600-E/R	3	S
80	Bo	131	Bobst SP 162-CER	3	S
90	Bo	131	Bobst SPO 1575	3	H
94	Bo	131	Bobst SPO 1600	3	H
98	Bo	131	Bobst SPO 203	3	H
15	lb	131	Iberica JR 105	2	S
40	lb	131	Iberica SR 144	3	S
KP	9	4	Additional threads for combi plate, per machine		
BM	30	13	Replacement Magnetic Mats, set of 4 pieces		